


Tech Sheet


Measuring a Small Arc


Steps to measure a circle with less than 90 degree's of arc:

1. Measure the small arc as a Measured Circle (a measured circle is used in this example although Auto Circle will also work).
 - Measure the circle on-line or
 - Pick it from the Model or
 - Key in the values
2. In this example, the back arc on the Hexagon Demo Block will be used.




3. Edit (**F9**) the circle.
 - Add additional hits.
 - Change the "Best Fit Math Type" to **"FIXED RAD"**.
 - Key in the **Nominal Diameter**.
 - Check **Regenerate Hit Targets**
 - Press **OK**.
 - When prompted "Ok to equally space hits?" answer YES.




4. Execute the feature **Ctrl E** to update the measured data.
5. Dimension the location  of the Fixed Radius circle. This will verify the location of the radius.
6. Enter the location Nominals and Tolerances.


#	IN	LOC4 - CIR 1					
AX	MEAS	NOMINAL	+TOL	-TOL	DEV	OUTTOL	
X	3.8797	3.8786	0.0100	0.0020	0.0011	0.0000	<input type="text"/>
Y	-5.7321	-5.7328	0.0100	0.0020	0.0007	0.0000	<input type="text"/>

7. Create an Alignment and set origin on Fixed Radius circle.





- Open the Parameter Settings Dialog **F10**. Select the Probing Tab and enable polar compensation for the active workplane.


 Note: Skip this step when using CAD and use Vector points rather than Measured points.




- With the joystick, measure 3 or more individual Measured Points on the Radius.

 Note: If you are using CAD, use Vector Points and pick from model.



10. Dimension the individual points using Location dimension  and select the " Prad" check box (Polar Radius). This will verify the size of the radius.



11. Enter Nominals and Tolerances for the Polar Radius'.

#	IN	LOC1 - PNT1					
AX	MEAS	NOMINAL	+TOL	-TOL	DEV	OUTTOL	
PR	9.9720	9.9705	0.0100	0.0100	0.0015	0.0000	

#	IN	LOC2 - PNT2					
AX	MEAS	NOMINAL	+TOL	-TOL	DEV	OUTTOL	
PR	9.9716	9.9705	0.0100	0.0100	0.0011	0.0000	

#	IN	LOC3 - PNT3					
AX	MEAS	NOMINAL	+TOL	-TOL	DEV	OUTTOL	
PR	9.9701	9.9705	0.0100	0.0100	-0.0004	0.0000	

12. Open the Parameter Settings Dialog **F10** and turn off polar compensation.